



GARY R. HERBERT
Governor

GREGORY S. BELL
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

Inspection Report Minerals Regulatory Program August 31, 2010

Reviewed: PRB

Mine Name: Camp Williams Mine	Permit Number: S/035/0037
Operator Name: Hadco Construction	Inspection Date: August 24, 2010
Inspector(s): L Heppler	Time: 9:00 am
Other Participants: none	Mine Status: Active

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Bond Renewal Date: 10-24-2010 **Bond Amount:** \$12,000

Purpose of Inspection: Operator requested bond release. This site has never been inspected as a small mine.

Inspection Summary: Area has been nicely regraded, site is dominated by weeds, there is an asphalt pile on the mine site and rockery berm on site. Two tires were found on site. See attached photographs, which were taken to document site conditions.

Conclusions and Recommendations: Site regrading bond release can be initiated after the asphalt pile is removed. Area should be roughed and reseeded with the attached seed mix for vegetation bond release. The operator should provide the Division documentation that the area has been reseeded twice. OGM to continue annual inspections and monitor the site when in the area.

Inspector's Signature

LAH:vs

Attachment - Seedmix

cc: Scott Roberts - Hadco Construction; Martin White - CMC Rock LLC

O:\M035-SaltLake\S0350037-CampWilliams\inspections\Insp-08242010.doc





Asphalt pile – to be removed



Entrance road thru the permit



Area north of entrance road - Note sunflower and Russian thistle



Area south of the entrance road – Area is dominated by Russian thistle

Recommended Revegetation Species List
for

Hadco Construction
Camp Williams Mne
S/035/0037

<u>Common Name</u>	<u>Species Name</u>	<u>*Rate lbs/ac (PLS)</u>
Intermediate wheatgrass	<u>Agropyron intermedium</u>	2.0
Bluebunch wheatgrass	<u>Agropyron spicatum</u>	3.0
Great basin wildrye	<u>Elymus cinereus</u>	2.0
Indian rice grass	<u>Oryzopsis Hymenoides</u>	2.0
Sandberg bluegrass	<u>Poa sandbergii</u>	0.5
Yellow sweetclover	<u>Melilotus officinalis</u>	0.5
Small burnet	<u>Sanguisorba minor</u>	1.0
Globemallow	<u>Sphaeralcea coccinea</u>	0.5
Palmer penstemon	<u>Penstemon palmeri</u>	0.5
Wyoming big sagebrush	<u>Artemisia tridentata wyomingensis</u>	0.2
Rubber rabbitbrush	<u>Chrysothamnus nauseosus</u>	0.25
Total		12.5 lbs/ac

***This is the recommended broadcast seeding rate.**

If the species are to be drill seeded, decrease the rate by 1/3.